



Update Detector Software to 2.3.2



Step 1: Check for Updates:


Ensure the Search Device is connected to a live (Wi-Fi or Cellular) network

From the Manage Detector screen in Field Console, select "Check for Updates"



Step 2: Download Update


Select "Download Update 2.3.2"



Step 3: Update Detector

Reconnect the Search Device (Field Console) to the Detector via the AirFlare_Admin network

Select "Update Detector to 2.3.2"



Step 4: OK to Continue

Select "OK" to continue